## Mercedes USB Media Interface

# Quick Software Upgrade Procedure

*Extract the umia2m.bin file if archived and copy it to the top directory of USB flash drive as shown below.*

| Name | Size | Date created |
|------|------|--------------|
| umia2m.bin | 1,095 KB | 5/15/2010 1:20 PM |

*Power the head unit and make sure that the media interface is running and is selected from the Audio CDC menu as shown below:*



*Plug the USB flash drive in the USB connector and the update will start immediately. A screen message will show "Updating Software"*



---

*An update takes about 30 seconds. After the update is completed the head unit will refresh the screen and will show the screen we started at*



*To update the Bluetooth software insert a USB flash drive with umi.dfu update file in the USB connector and the update will start immediately*



*The screen will show "BT Software Update" and the track timing will show the progress 0 to 99 on the minutes and 0 to 05 on the seconds*



*An update takes about 7 minutes. After the update is completed the screen message will show that the update is successful and return to initial screen*



---

*To check the software revisions select CD6 key and press once SEEK+ to the second menu called "Settings menu"*



*Press and hold SEEK+ key and the current software version will be displayed on the screen starting with MB*



*Press once SEEK+ and the current Bluetooth software version will be displayed on the screen starting with BT*



*Press once SEEK+ and the screen will show a "Reset" menu. To manually reset the system press and hold SEEK+ at this step*